Work Order ID 55367

January 14, 2010 2:24:43 PM



Page 1

Item ID:

DSI 9396-011

Accept



Setup Start

Stop



Revision ID:

Item Name:

Fwd Crosstube Support Change

Start Date:

Required Date: 1/15/2010

1/14/2010

QC:

Start Qty: 1.00

Req'd Qty: 1.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan: MF

Date: 10-/-14 Tooling:

Date:

Run

Start

Date:

SPC (Y/N):

Date:

Stop

Sequence ID/ **Work Center ID** **Operation** Description Set Up/ **Run Hours**

Draw Number Draw Rev.

Plan Accept Code Qty

Reject Qty

Reject Number Stamp

Draw Nbr

Revision Nbr

DSI 9396

Rev B

DOCUMENT CONTROL

Document Control

QC4-100% Inspect kits for completeness

Memo

Photocopy bluefile and create labels as per PPP DSI 9396 CHG001

MF 10-1-14

Swolowly

110

100

Memo

0.00

0.00

0.00

Quality Control

120

Packaging

Packaging

0.00

Memo

0.00

Packaging

Identify and pack for shipping as per PPP DSI 9396 Location: _____ DPPP Rev: DNDFF /-1/1/19 O

Dart Aerospace I	Ltd	
------------------	-----	--

W/O:			WO	RK ORDER CHANG	ES	1			
DATE	STEP	PROCEDURE CHANGE				Da	ate Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
:									
			PAR #: PAR #: NCR:						
			Disposition	:	QA: N/C Closed: Date				
NCR:			WORK ORDE	R NON-CONFORMA	ANCE (N	CR)			
DATE	STEP	Description of NC	Corrective Action Section				/erification	Approval	Approval
DAIL	JILF	Section A	Initial Chief Eng	Action Description Chief Eng		n & ' ite	Section C	Chief Eng	QC Inspector
						- - -			
				***************************************			W W		1

Work Order ID 55367

January 14, 2010 2:24:43 PM



Page 2

Item ID:

DSI 9396-011

Accept



Setup Start

Stop



Revision ID:

Item Name:

Fwd Crosstube Support Change

Start Date:

Required Date: 1/15/2010

1/14/2010

Start Qty: 1.00

Req'd Qty: 1.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Date:

Tooling:

Date:

Date:

Run

Stop

Start

Sequence ID/

Operation Work Center ID

QC:

Description

QC21- Final Inspection - Work Order Release

Set Up/ **Run Hours**

SPC (Y/N):

Draw Number Draw Rev.

Plan Code

Accept Qty

Reject Reject Qty

Insp. Number Stamp

130

Memo

0.00

0.00

Quality Control

Dart Aerospace Ltd

		— - 								
W/O:		NH	W	ORK ORDER CHAN	GES					
DATE	STEP	PROCEDURE CHANGE					Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•	PAR #:	Fault Cate	gory:	NCR:	Yes N	o DQ	\:	Date:	
	Re	esolution:	Disposition	n:	QA: N	/C Clos	sed:		Date: _	
NCR:			WORK ORD	ER NON-CONFORM	MANCE (NCR)				
DATE	STEP	Description of NC Section A	Initial	Corrective Action Se Action Description		ign &	Verific Section		Approval Chief Eng	Approval QC Inspector
			Chief Eng	Chief Eng		Date	CCCIII		J. 1.0. 2.1.9	do moposici

Picklist Print

January 14, 2010 2:24:43 PM

Work Order ID: 55367

Parent Item:

Component Item ID/

Comments:

Item Name

D3595-063-450

DSI 9396-011

Parent Item Name: Fwd Crosstube Support Change

IPP Rev:A

New Issue 07-12-17 DD

Replacement Mfg/ Item ID

Purch

Manufactured

Primary Bin Item Location

No

verified by: EC

Location

Last

Route Seq ID 110

Each

Unit of

Qty To Pick Issued Measure Hand

Qty on

164.1266 4.0000

Start Qty: 1.00

Remaining

Qty

Start Date: 1/14/2010

Required Date: 1/15/2010

Required Qty: 1.00

Date

Issued

RUBBER CUSHION

Warehouse	Loc Qty	Loc Code	
Location			
Main Warehouse			
LG	59.15767369		
52447	59.1576737		52447
Main Warehouse			// -
ST	104.9689		
38959	2		
43210	2.59		
46465	0.3789		
53775	100		

Status

Dart Aerospace Ltd

W/O:			WO	RK ORDER CHANG	ES				
DATE	STEP	PROCEDURE CHANGE					ate Qty	Approvat Chief Eng / Prod Mgr	Approval QC Inspector
								-	
Part No	:	PAR #:	Fault Categ	jory:	NCR: Ye	es No	DQA:	Date: _	
	R	esolution:	Disposition	:	_ QA: N/C	Closed	d:	Date: _	
NCR:			WORK ORDE	R NON-CONFORM	ANCE (N	CR)			
DATE	STEP	Description of NC	Corrective Action Section			,	/erification	Approval	Approval
	O12.	Section A	Initial Chief Eng	Action Description Chief Eng		n &	Section C	Chief Eng	QC Inspector
									:

January 14, 2010 2:24:43 PM

Work Order ID: 55367

Parent Item:

DSI 9396-011

Parent Item Name:

Fwd Crosstube Support Change

Comments:

IPP Rev:A

New Issue 07-12-17 DD



Start Date: 1/14/2010

Required Date: 1/15/2010

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name

Replacement Mfg/ Item ID

Purch

Purchased

Primary Bin Location Item

No

verified by: EC

Warehouse

Last Location Route Seq ID

110

Unit of Measure

Each

177

2 3

17

42

10

Qty on Hand

Remaining Qty Qty To Pick Issued Date Issued Status

MS21920-25

Clamp(per MIL-DTL-8783C)

Loc Qty Loc Code

Location Main Warehouse ST 107456 108111

108975 109181 109644 111282 111429

112495 112919 22 113281 25 113282 50

177.0000 4.0000

W/O:			W	ORK ORDER CHANG	ES					
DATE	STEP	PROCEDURE CHANGE					Date	Qty	Approvat Chief Eng / Prod Mgr	Approval QC Inspector
						į				

Part No	:	PAR #:	Fault Cate	gory:	_ NCR:	Yes N	lo DQ A	\:	Date:	
Resolution:			Disposition	_ QA: I	QA: N/C Closed: Date:					
NCR:			WORK ORD	ER NON-CONFORM	ANCE	(NCR)				
DATE	STEP	Description of NC	Corrective Action Section B Initial Action Description			Verifica			Approval	
		Section A	Chief Eng	Chief Eng		Date	Section	on C	Chief Eng	QC Inspector
							·			
										,
								_		
			-							

For customers who would like to upgrade their D205-596-101/-103/-105/-107 Crosstubes from CHG 001 to CHG 002, the following kits can be obtained from Dart:

DSI 9396-XXX PARTS LIST

∕ QTY -011	QTY / -013	Part Number	Description
X		DSI 9396-011	FWD CROSSTUBE SUPPORT CHANGE (D205-596-101/-105 FWD CROSSTUBE)
	Х	DSI 9396-013	AFT CROSSTUBE SUPPORT CHANGE (D205-596-103/-107 AFT CROSSTUBE)
4		D3595-063-450	RUBBER CUSHION
/4		MS21920-25	CLAMP
	4	D3595-063-530	RUBBER CUSHION
	4	MS21920-28	CLAMP




FIGURE 1: INSTALLATION OF SUPPORT ON CROSSTUBE

